



# HURRICANE BERYL IN JAMAICA

---

Group 7







# BERYL AND ITS IMPACTS

Hurricane Beryl, a powerful tropical cyclone that occurred in the Caribbean region. Beryl made a significant impact in the Caribbean region with winds ranging from 140 to 160 mph, Beryl became the first hurricane of the 2024 Atlantic season. Notably, it achieved the strongest possible ranking of Category 5, marking the earliest storm on record to reach this intensity in Jamaica.

## The Impacts

- Roof Damage
- Crop Loss
- Disruption in Power grid
- Flooding
- Road Damage
- Infrastructure Damage





# FACTORS OF THE IMPACT

- Poor Waste Management
- Inadequate Drainage
- Poor infrastructure Management
- Poor Planning & Preparedness







# SOLUTION TO MITIGATE THE EFFECTS OF BERYL

- Effective **Drain Cleaning**
- Community Emergency Response Teams (**CERTS**)
- Enforcement of **Building codes** and regular inspection of buildings







# THANK YOU

The picture on the cover page was captured by the international space station.  
The picture with the zinc was taken by Joe Raedle / Getty Images.  
The pictures on page 4 are from, Jamaica Live and RJR.  
All the other images are from Rhea Millwood.

Record-breaking Hurricane Beryl threatens Caribbean. World Meteorological Organization. (2024, July 8). <https://wmo.int/media/news/record-breaking-hurricane-beryl-threatens-caribbean>

